



## Wax Recommendations

### HS – 30 Series

Effective Temperature Range: 22 to 32 F

Optimal Temperature Range: 25 to 30 F

#### Basic Paraffin Wax

... *Fast, Simple and Inexpensive using Fast Wax Sport Wax*

1. Base Prep      Clean your skis with Base Prep and scrape while warm
2. HS-30 Red      Apply 2 layers of HS-30 Red Sport Wax  
Scrape and brush between layers

#### Low Fluoro

... *Fast, Simple and Durable –Still quick and easy using Fast Wax Low Fluoro Racing Wax*

1. Base Prep      Clean your skis with Base Prep and scrape while warm
2. HS-30 Red      Apply 1 layer of HS – 30 Red, Scrape and brush
3. HSLF-30 Red    Apply 2 layers of HSLF-30 Red Low Fluoro Racing Wax  
Scrape and brush between layers

#### High Fluoro

... *Fast, Simple and More Durable –Still quick and easy using Fast Wax High Fluoro Racing Wax*

1. Base Prep      Clean your skis with Base Prep and scrape while warm
2. HS-30 Red      Apply 1 layer of HS – 30 Red, Scrape and Brush
3. HSF-30 Salmon    Apply 2 layers of HSF - 30 Salmon High Fluoro Racing Wax  
Scrape and brush between layers

#### Pure Fluoro Flite Top Coat

... *Takes time but is worth the effort for long lasting speed  
Flite is most effective when the temperatures are above 24 F with high humidity*

1. Base Prep      Clean your skis with Base Prep and scrape while war
2. HS-30 Red      Apply 1 layer of HS – 30 Red. Scrape and brush
3. HSF-30 Salmon    Apply 2 layers of HSF - 30 Salmon High Fluoro Racing Wax  
Scrape and brush between layers
4. Flite-11 Warm    Cork or Iron Fast Wax Flite 11 Warm Speed Additive

**For new snow use a Universal Structure or Universal Plus Structure  
For old or transformed snow use a Universal Plus with a light Rill**

Visit our web site at [www.skifastwax.com](http://www.skifastwax.com) for more waxing tips and recommendations